

MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

CRAFT TEXTILE

27220136-outlets 1 & 2

1. MONTH OF APRIL 1, 2008 THRU APRIL 30, 2008
2. Is Outlet # (8 digit) Correct? ☒ Y N N/A
3. Is average Total flow-gal.day stated in space provided? ☒ Y N N/A
4. Is max. Total flow-gal day stated in space provided? ☒ Y N N/A
5. Is method used to calculate water stated? ☒ Y N N/A
6. Are number of working days stated? ☒ Y N N/A
7. Are there any parameters which have exceeded PVSC Local Limits? Y ☒ N N/A
8. Is proper compliance/non-compliance statement provided? ☒ Y N N/A
9. Have correct number of samples been submitted? ☒ Y N N/A
10. Has PHC result been listed on MR-1 report? Y N ☒ N/A
11. Has sample number been reported in space provided? ☒ Y N N/A
12. Have all regulated parameters been listed on MR-1? ☒ Y N N/A
13. Has sample type been stated on MR-1? ☒ Y N N/A
14. Have all samples been taken during this reporting period? ☒ Y N N/A
15. Has NJDEP certified lab been used? ☒ Y N N/A
16. Have analytical results been submitted on copies of Laboratory stationery? ☒ Y N N/A
17. Have results been written in space designated on MR-1? ☒ Y N N/A
18. Is correct method used to preserve samples stated on MR-1? ☒ Y N N/A
19. Has MR-1 been signed by authorized representative? ☒ Y N N/A
20. Has information been submitted on proper MR-1 form? ☒ Y N N/A
21. Remove Arsenic from report if sampling not required Y N ☒ N/A

MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

Craft Textile

27220136

First Reviewer: comments on deficiencies COMPLETEDate Reviewed 6/9/08 Date sent to user _____Date due back _____ Reviewer C.J.M.Second review comments on deficiencies

Date Reviewed _____ Date sent to user _____

Date due back _____ Reviewer 

Date _____ Reviewer _____

PRETREATMENT MONITORING REPORT

NAME: Craft Textile Printing Co., Inc.
 MAILING ADDRESS: P.O. Box 2761, Paterson, NJ 07509-2761
 FACILITY LOCATION: 44 Beech Street, Paterson, NJ 07501
 Category & Subpart: 9999
 Contact Official: H.R. Casparian
 New Customer ID/Outlet ID: 27220136-1

OUTLET # 1

Telephone # 973-278-3818

Old Outlet Designation: 27400061



MONITORING PERIOD

START	END
4/1/2008	4/30/2008
m/d/yr	m/d/yr

Regulated Flow(gal/day)

Total Flow (gal/day)

Average Maximum

N/A

25922 28514

Method Used:

Gallons in less 5% evap. divided by
 production days in month (15)

Production Rate:

N/A

Parameter		Mass or Concentration			# of Samples	Sample Type
		Mon Avg	Maximum	Units		
Zinc	Sample Measurement	0.0614		mg/l	1	Comp
	Permit Requirement	1.67		mg/l		
Copper	Sample Measurement	0.0233		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					

PVSC Form MR-1 Rev: 4 6/87 P1



Certification of Non-Use if applicable (use additional sheets)

~~NOT~~ N/A

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits:	ZN , CU	> Local Limits:	N/A
< Threshold Values	ZN , CU	> Threshold Values:	N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610, October 17, 1988

Signature of Principal

H.R. Casparian
executive or authorized agent

H.R. Casparian-President

Name-Title

5/2/2008

Date

PVSC Form MR-1 Rev: 5 3/91 P2

PRETREATMENT MONITORING REPORT

NAME: Craft Textile Printing Co., Inc.
 MAILING ADDRESS: P.O. Box 2761, Paterson, NJ 07509-2761
 FACILITY LOCATION: 44 Beech Street, Paterson, NJ 07501
 Category & Subpart: 9999 OUTLET # 2
 Contact Official: H.R. Casparian Telephone # 973-278-3818
 New Customer ID/Outlet ID: 27220136-2 Old Outlet Designation: 27400062



MONITORING PERIOD

START	END
4/1/2008	4/30/2008
m/d/yr	m/d/yr

Average Maximum
 Regulated Flow(gal/day) N/A
 Total Flow (gal/day) 15031 16534

Method Used:

Gallons in less 5% evap. divided by
 production days in month (15)

Production Rate: N/A

Parameter		Mass or Concentration			# of Samples	Sample Type
		Mon Avg	Maximum	Units		
Zinc	Sample Measurement	0.121		mg/l	1	Comp
	Permit Requirement	1.67		mg/l		
Copper	Sample Measurement	0.0139		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
Lead	Sample Measurement	0.0069		mg/l	1	Comp
	Permit Requirement	.029/.54		mg/l		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					

PVSC Form MR-1 Rev: 4 6/87 P1



Certification of Non-Use if applicable (use additional sheets)

N/A

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits: ZN , CU , PB	> Local Limits: N/A
< Threshold Values ZN , CU , PB	> Threshold Values: N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610, October 17, 1988

Signature of Principal

H.R. Casparian
executive or authorized agent

H.R. Casparian-President

Name-Title

5/2/2008

Date

PVSC Form MR-1 Rev: 5 3/91 P2



CHAIN OF CUSTODY RECORD

284 Sheffield Street, Mountainside, NJ 07092
(908) 789-8900 Fax (908) 789-8922
www.chemtech.net

CHEMTECH PROJECT NO.

QUOTE NO.

COC Number

7213

070543

CLIENT INFORMATION				CLIENT PROJECT INFORMATION				CLIENT BILLING INFORMATION							
REPORT TO BE SENT TO:				PROJECT NAME:				BILL TO:							
COMPANY: CRAFT TEXTILE PRINTING Co., Inc.				PROJECT NO.:				ADDRESS:							
ADDRESS: P.O. Box 2761				LOCATION:				CITY:							
CITY: PATERSON STATE: NJ ZIP: 07509				PROJECT MANAGER:				ATTENTION:							
ATTENTION: H.R. CASPARIAN				e-mail:				PHONE:							
PHONE: 973-278-3818 FAX: 973-523-8677				PHONE:				FAX:							
DATA TURNAROUND INFORMATION				DATA DELIVERABLE INFORMATION				ANALYSIS							
FAX: _____				RESULTS ONLY <input type="checkbox"/> USEPA CLP				PRESERVATIVES							
HARD COPY: _____				RESULTS + QC <input type="checkbox"/> New York State ASP "B"											
EDD: _____				<input type="checkbox"/> New Jersey REDUCED <input type="checkbox"/> New York State ASP "A"				COMMENTS							
PRE-APPROVED TAT: <input type="checkbox"/> YES <input type="checkbox"/> NO				<input type="checkbox"/> New Jersey CLP <input type="checkbox"/> Other _____											
STANDARD TURNAROUND TIME IS 10 BUSINESS DAYS				<input type="checkbox"/> EDD FORMAT				--- Specify Preservatives A-HCl B-HNO ₃ C-H ₂ SO ₄ D-NaOH E-ICE F-Other							
CHEMTECH SAMPLE ID	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	SAMPLE TYPE	SAMPLE COLLECTION DATE	TIME	# OF BOTTLES	1	2	3	4	5	6	7	8	9
1.	Outlet #1	X	42108	NOON	2	2	X	X							
2.	Outlet #2	X	42108	NOON	2	2	X	X							
3.															
4.															
5.															
6.															
7.															
8.															
9.															
10.															

SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY			
RECEIVED BY:	DATE/TIME:	RECEIVED BY:	DATE/TIME:
1. H.R. Casparian	4/21/08/NOON	1. L. Jackson	4/21/08/NOON
2. H.R. Casparian	4/22/08/4:20	2. S. H. H. H.	4/22/08/4:20
3. S. H. H. H.	4/22/08/4:20	3. S. H. H. H.	4/22/08/4:20

COOLER INFORMATION: Cooler Temp. 5°C Ice in Cooler? Yes

SHIPPED VIA: CLIENT: ☐ HAND DELIVERED ☐ OVERNIGHT ☐ PICKED UP ☐ OVERNIGHT ☐ NO

Page 1 of 1

WHITE - CHEMTECH COPY FOR RETURN TO CLIENT YELLOW - CHEMTECH COPY PINK - SAMPLER COPY



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

Report of Analysis

Client:	Craft Textile Printing	Date Collected:	4/2/2008
Project:	Permit Renewal 2008	Date Received:	4/2/2008
Client Sample ID:	OUTLET-1	SDG No.:	Z2213
Lab Sample ID:	Z2213-01	Matrix:	WATER
		% Solids:	0.00

CAS No.	Analyte	Conc.	Qualifier	Units	DL	Dilution	Date Prep	Date Anal.	Method
7440-50-8	Copper	23.3		ug/L	3.4	1	4/4/2008	4/7/2008	EPA SW-846 200.7
7440-66-6	Zinc	61.4		ug/L	1.9	1	4/4/2008	4/7/2008	EPA SW-846 200.7

Comments:

U = Not Detected
DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value
B = Analyte Found In Associated Method Blank
N = Spiked sample recovery not within control li



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

Report of Analysis

Client:	Craft Textile Printing	Date Collected:	4/2/2008
Project:	Permit Renewal 2008	Date Received:	4/2/2008
Client Sample ID:	OUTLET-2	SDG No.:	Z2213
Lab Sample ID:	Z2213-02	Matrix:	WATER
		% Solids:	0.00

CAS No.	Analyte	Conc.	Qualifier	Units	DL	Dilution	Date Prep	Date Anal.	Method
7440-50-8	Copper	13.9		ug/L	3.4	1	4/4/2008	4/7/2008	EPA SW-846 200.7
7439-92-1	Lead	6.9	J	ug/L	2.2	1	4/4/2008	4/7/2008	EPA SW-846 200.7
7440-66-6	Zinc	121		ug/L	1.9	1	4/4/2008	4/7/2008	EPA SW-846 200.7

Comments:

U = Not Detected
DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value
B = Analyte Found In Associated Method Blank
N = Spiked sample recovery not within control li

7

NON USE CERTIFICATION MONITORING REPORT **LOCAL LIMITS**

NAME: CRAFT TEXTILE

MAILING ADDRESS: _____

CILITY LOCATION: _____

TEGORY & SUBPART _____

PERMIT # _____

OUTLET #: 27220130-2

CONTACT OFFICIAL: _____

TELEPHONE #: _____

I have been authorized to certify non-use for the following heavy metals:

enic _____ Lead ☒ _____ Zinc _____
 Iridium _____ Mercury _____
 Radium _____ Molybdenum _____
 per ☒ _____ Nickel _____

SAMPLE DATE			
MONTH	DAY	YEAR	
4	2	08	

PARAMETER		CONCENTRATION			SAMPLE TYPE
		RESULT	THRESHOLD VALUE EXCEEDED YES OR NO	UNITS	COMP/GRAB
COPPER	Sample Measurement	0.0139	n	mg/l	Comp.
	Threshold Value	0.092		1	
LEAD	Sample Measurement	0.0069	n	mg/l	comp.
	Threshold Value	0.029		1	
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				

PVSC Form MR-3 10/96